

TECHNICAL F329

SOFT 12

CHARACTERISTICS

A Soft Sheen Emulsion paint recommended for all interior surfaces. The product is particularly suitable for kitchens, bathrooms and other areas where a heavy duty, wipe clean is required.

COLOUR

Brilliant White and various colours from Colour Answers Tinting Machine.

DRYING SCHEDULE

(Temperature and humidity dependant) @ 26°C 50% RH @ 4 Thou wet. To Touch - 30 mins To Dry - 4 hours

SPECIFIC GRAVITY

1.192+/-0.01

WEIGHT SOLIDS

38+/-1%

VOLUME SOLIDS

PRECAUTIONS

Do not take internally.

Contains no added lead.

Keep out of reach of children. Ensure good ventilation during application and drying.

In case of contact with eyes rinse immediately with plenty of water.

To remove splashes from skin use soap and water or a recognised skin cleaner.

27+/-1%

APPLICATION

Temperature (air, surface, material) (at least 4°C above dew point) 10°C to 42°C. Relative Humidity 75% Maximum.

SPREADING RATE

120m²/10lt 60m²/5lt 30m²/2.5lt

METHODS

Brush, roller, airless spray. Airless Spray:- Minimum pressure 138 bars (2000lb.sq in).

Tip Size:- 0.38mm - 0.46mm (15-18 Thou).

Filter:- 60 mesh. Angle:- 65 degrees

Always flush spray equipment with water prior to applying Water Based coatings.

MIXING INSTRUCTIONS

Thoroughly mix paint before use by stirring and boxing.

TINTING INSTRUCTIONS

Tint only with the Fleetwood Tinting System.

CLEAN UP

Clean up with soap and water. After clean up be sure to flush spray equipment with solvent to prevent rusting following manufacturers instructions

REDUCTION

Reduce up to 10% with water as required by application equipment.

SURFACE PREPARATION

Surfaces to be painted must be in sound condition. Use in accordance with good painting practice. Remove wax, rust, grease, oil, flaking material and powdery substances. Lightly sand glossy surfaces. Follow by thoroughly washing with detergent and rinsing with clean water. Check coloured and gold marked wallpaper for colour bleeding through. If this occurs, apply an appropriate sealer. Allow to dry. Areas with uneven porosity may require a coat of Water Based Stabilising Solution.

Steel:- Remove all loose rust, peeling paint, other loosely adhering contamination per SSPC SP2. Hand tool cleaning. Remove any contamination before applying subsequent coats of material. Prime base steel with an appropriate anti-corrosive primer.

Concrete Block and Masonry:- Surfaces should be thoroughly clean and dry, with mortar and concrete aired for a minimum of 30 days @ 24°C. All loose mortar or other contaminants should be removed prior to application of any coating material. Surface temperatures must be at least 12°C before filling. Use appropriate filler for cracks or imperfections. Allow to dry thoroughly before top-coating.

PREVIOUSLY PAINTED SURFACES

If in sound condition, clean the surface of all foreign material. Glossy surfaces must be rubbed down to provide a key. If paint is peeling or badly weathered, clean to sound substrate and treat as new.

ISSUE NO.1 6/2008

Fleetwood Paints Ltd/FSW Coatings Ltd., Virginia, Co.Cavan. Ireland. Tel +353 49 8547209 Fax +353 49 8547470

Email: info@fleetwood.ie info@fsw.ie Web: www.fleetwood.ie